

There are two amendment on HB1B need to be done after we came cross the bulk testing during the shipment.

1. For R3, original is 33ohm, exchange it with a 18ohm or parallel connection of a 47ohm.

This will help to improve the 80M band harmonics if the power supply lower than 11VDC.

2. For C21, cancel it or exchange it with a 4700P.

This will help to cancel the possibility of no output when use straight key.

Any new shipment after Nov.24 will be changed on these two point.

Thank you!

Youkits

2011-Nov-24